

## 2 Pack Rope Pull Starter Pawl 2-80 HP Rewind Pawl EMP

MPN : 300-01744



Model : 300-01744

Manufacturer : EMP

Brand NEW EMP Johnson Rope Pull Starter Pawl 2 Pack.

1 Package Repairs  
2 Starter Pawls  
300-01744 or 18-6513

Replaces 203698

Application Details  
For Motors Using OE# 203698  
Replaced by Sierra 18-6513

HP	Year	Sierra PN
2	1971-88	18-6513
Jr/Colt	1990	18-6513
3	1957-67	18-6513
4	1978-90	18-6513
5.5	1957-64	18-6513
7.5	1957-76	18-6513
10	1957-62	18-6513
18	1957-73	18-6513
25	1969-76	18-6513
25	1977	18-6513
35	1976-77	18-6513
45	1958-59	18-6513
50	1958-89	18-6513
60	1964-66	18-6513
75	1960-65	18-6513
80	1966	18-6513

**Price : \$4.99**

Availability: This product was added to our catalog on Thursday 13 June, 2019