

2 Pack Rope Pull Start Starter Pawl 20-35 HP Rewind Pawl EMP



Model : 300-01633

Manufacturer : EMP

Application Details
For Motors Using OE# 330525

HP	Year	Sierra PN
20	1981-90	18-6512
25	1978-90	18-6512
25C	1982-90	18-6512
30	1957-61	18-6512
30	1984-90	18-6512
35	1978-90	18-6512

1 Package Repairs
2 Starter Pawls

Replaces 330525, 18-6512
EMP Part Number 300-01633

Price : \$3.99

Availability: This product was added to our catalog on Tuesday 04 June, 2019